



Parth Dixit <[parth.dixit@linaro.org](mailto:parth.dixit@linaro.org)>

---

## [PATCH RFC 17/35] pl011: Initialize serial from ACPI SPCR table

---

Ian Campbell <[Ian.Campbell@citrix.com](mailto:Ian.Campbell@citrix.com)>

5 February 2015 at 20:22

To: Julien Grall <[julien.grall@linaro.org](mailto:julien.grall@linaro.org)>

Cc: [parth.dixit@linaro.org](mailto:parth.dixit@linaro.org), [xen-devel@lists.xen.org](mailto:xen-devel@lists.xen.org), [stefano.stabellini@citrix.com](mailto:stefano.stabellini@citrix.com), [tim@xen.org](mailto:tim@xen.org), [jbeulich@suse.com](mailto:jbeulich@suse.com), [christoffer.dall@linaro.org](mailto:christoffer.dall@linaro.org), Naresh Bhat <[naresh.bhat@linaro.org](mailto:naresh.bhat@linaro.org)>

[Quoted text hidden]

Remember that things like the probe function are going to have different prototypes. It also contains things like the DT compat list which is DT specific.

So, I think the macros should remain boot firmware specific, whether they fill in the same array or not is an implementation detail, but it would seem less error prone to split them up.

Ian.